

U.S. Department of Transportation

National Highway Traffic Safety Administration

Memorandum

(NHTSA-2001-9628-34 (NHTSA-2001-9630-33

Subject:

Request to Place Comments in the Dockets Regarding Decisions for 2001 Ferrari

Date: DEC 1 0 2001

360 and 550 Passenger Cars

300 did 330 Eastenger

DEC 10 2001

From:

Coleman Sachs Attorney

Reply to

FIUIII.

To:

Docket Management

Please place the attached documents regarding whether nonconforming 2001 Ferrari 360 and 550 passenger cars are eligible for importation, as requested in Petition Nos. 484 and 485, in both Docket Nos. NHTSA-2001-9628 and NHTSA-2001-9630.

Attachments

#



Jonathan Weisheit, President J. K. Technologies, L.L.C. 3500 Sweet Air Street Baltimore, MD 21211

RE: Confidentiality Determination/Comments to Docket Nos. NHTSA-2001-9628/9630

Dear Mr. Weisheit:

This is in response to your letters dated October 3 and October 5, 2001, in which you request confidential treatment for information contained in your comments dated October 4, 2001, to the Petitions in the above referenced Dockets, enclosed with your submission. Specifically, you request confidential treatment for "data, photographs, drawings, Inter-company parts lists and engineering drawings along with the calculations supporting these submissions." You request confidential treatment for this information for a period of eight (8) years.

You assert that J. K. Technologies, L.L.C. has internally developed this information through "extensive and expensive testing" and design, and that its release "would result in substantial competitive harm to our organization as it would give our competitors a 'recipe' for the modification necessary to bring the 360 and 550 [Ferrari] models into compliance with all of the FMVSS [Federal Motor Vehicle Safety Standard]." You assert also that the Office of Chief Counsel (OCC) has previously granted confidential treatment for "similar compilations" of parts lists for Ferrari and that "Release of our data with [its] supporting engineering and drawings would literally be providing a blueprint and not just a recipe." In addition, you assert that this information "constitutes a major part of the intellectual and engineering property of the company as a whole" and that its release would allow "direct and indirect competitors in the industry [to] have a virtual blueprint of the engineering required to bring the vehicles into conformity with FMVSS without having to develop any systems of their own." Finally, you assert that "This compilation of information in total, has not been disclosed or otherwise made available to any other person, company or organization other than the submitter."

I have reviewed your submission, including the materials that you claim are entitled to confidential treatment and the arguments that you assert in support of your claim. While I have not reached a conclusion regarding each individual argument that you assert, I have

concluded based upon your submission as a whole that the materials submitted were provided voluntarily and are not customarily disclosed to the public. See Critical Mass Energy Project v. NRC, 975 F.2d 871, 879 (D.C. Cir. 1992). Therefore, I have decided to grant confidential treatment to these materials under Exemption 4 of the Freedom of Information Act, 5 U.S.C. § 552(b)(4). The information will be protected for the period of time you request (until October 3, 2009).

This grant of confidential treatment is subject to certain conditions. The information that has been granted confidential treatment may be disclosed under 49 CFR § 512.8, based upon newly discovered or changed facts, and you must inform the agency of any changed circumstances which may affect the protection of the information (49 CFR § 512.4(i)). Prior to the release of information under 49 CFR § 512.8, you would be notified in accordance with the procedures established by our regulations.

Sincerely,

Heidi L'. Coleman

Assistant Chief Counsel


for General Law

NCC-30:wilson:61834:10/11/01:23665

NCC-30:sub/chron

NSA-32.2:Entwistle (w/appendix)

U:\ncc30\conf\misc01\JK Tech.23665.kvw.doc



U.S. DEPARTMENT OF TRANSPORTATION

NATIONAL HIGHWAY
TRAFFIC SAFETY
ADMINISTRATION

OFFICE OF
VEHICLE SAFETY
COMPLIANCE

Rm 6115, NSA-32 400 7th St., SW Washington, DC 20590

PRANS NPITTAL

FAX NUMBER: (202) 366-1024

Attachment 2

DATE: November 6, 2001

FROM: Luke Loy

TELEPHONE NUMBER: (202) 366-5308

TO: Mr. David Wertheim

Company: Ferrari North America

FAX NUMBER: 201-541-0038

<u>MESSAGE:</u> Request for Additional Information regarding the Ferrari 360 Modena/Spyder and 550 Marinello/Barchetta.

In order to evaluate comments made by both J.K. Technologies, and Ferrari North America we request the following information.

- 1. The parts page printout for the airbag/knee bolster showing part numbers for the Ferrari 550.
- 2. Are the U.S. version 360 Modena/Spyder and the 550 Marinello-Barchetta equipped with airbag cut-off switches?
- 3. Regarding the fuel tanks for the Ferrari 360/Ferrari 550--What are the differences between European and U.S. fuel tanks? Are there size, shape, wall thickness differences? Are the fuel tanks structured differently, located differently, fabricated differently, different location of inlets and outlets on the tank? Are the fuel lines, vent lines located differently around the tanks? Please provide an exploded view drawing of the general area around each fuel tank, for both the 360 and 550.
- 4. The roof structure of the 550 Coupe is different from the U.S. version to the European version. What is the method of fabrication of the roof structure?
- 5. Identify differences in the rear frame assembly between the U.S. and non-U.S. version vehicle for both the 360 and the 550 vehicles.

Please provide response by November 13, 2001, phone me if you have additional questions.

Luke Lov

Import Certification and Compliance Engineer

Attachment 3

MAYER, BROWN & PLATT

1909 K STREET, N.W.

WASHINGTON, D.C. 20006-1101

ADAM C. SLOANE
DIRECT DIAL (202) 263-3269
DIRECT FAX (202) 263-5269
asicane@mayerbrown.com

MAIN TELEPHONE (202) 263-3000 MAIN FAX (202) 263-3300

November 14, 2001

By Facsimile and UPS

Luke Loy Import Certification and Compliance Engineer National Highway Traffic Safety Administration 400 Seventh Street, S.W., Rm. 6115, NSA-32 Washington, D.C. 20590

Re: Docket Nos. NHTSA-2001-9628 and NHTSA-2001-9630 – Request for Additional Information Regarding the Ferrari 360 Modena/Spyder and 550 Maranello/Barchetta

Dear Mr. Loy:

Ferrari North America, Inc. ("FNA"), through its undersigned counsel, hereby responds to your request (dated Nov. 6, 2001) for additional information regarding the Ferrari 360 Modena/Spyder and 550 Maranello/Barchetta in connection with above-referenced dockets. Your request contains five separately numbered items. For your convenience, we will set forth each numbered request in bold-face type together with FNA's response to each.

1. The parts page printout for the airbag/knee bolter showing part numbers for the Ferrari 550.

The requested printout is attached hereto as Attachment 1.

2. Are the U.S. version 360 Modena/Spyder and the 550 Maranello-Barchetta equipped with airbag cut-off switches?

No.

3. Regarding the fuel tanks for the Ferrari 360/Ferrari 550 – What are the differences between European and U.S. fuel tanks? Are there size, shape, wall thickness differences? Are the fuel tanks structured differently, located differently, fabricated

CHARLOTTE CHICAGO COLOGNE FRANKFURT HOUSTON LONDON LOS ANGELES NEW YORK PALO ALTO PARIS WASHINGTON INDEPENDENT HEXICO CITT CORRESPONDENT: JAUREGUI, NAVARRETE, NADER Y ROJAS

MAYER, BROWN & PLATT

Luke Loy November 14, 2001 Page 2

differently, different location of inlet and outlets on the tank? Are the fuel lines, vent lines located differently around the tanks? Please provide an exploded view drawing of the general area around each fuel tank, for both the 360 and 550.

The requested drawings are attached hereto as Attachment 2. Although the fuel tanks are fabricated using the same materials and methods, and are similarly located, there are significant differences between the U.S. and non-U.S. versions of the fuel tanks:

- The U.S. 360s' left side fuel tank has a fuel filler neck opening that is different in diameter from the opening on the non-U.S. versions.
- Unlike the non-U.S. versions, the U.S. 360s' right side fuel tank has a fuel pressure sensor mounted in the top of the tank.
- The shape of the U.S. 550s' fuel tank is different from the shape of the non-U.S. version. This is attributable to the fitting of the vapor separator and the additional openings for the various lines.
- The U.S. 550s' fuel tank is fitted with a temperature sensor that is not present on the non-U.S. versions.
- There are volume (capacity) differences between the U.S. and non-U.S. versions of the 360s and 550s. These volume differences are attributable to the different components of the tanks, and, in the case of the 550, to the difference in shape.

The differences identified above are reflected in Attachment 2, which includes pages from the parts catalogues for the 360s and 550s. In addition, the attachment shows the different lines and hoses for the fuel tank system. It should be noted that the 550 parts catalogue includes a page for the U.S. versions and a different page for the non-U.S. versions. The blueprints that display the differences between the U.S. and non-U.S. versions are available from the factory and will be supplied to the agency upon request.

4. The roof structure of the 550 Coupe is different from the U.S. version to the European version. What is the method of fabrication of the roof structure?

Both the U.S. and European versions of the roof structure of the 550 Coupe are welded and riveted. However, as noted in Erika Z. Jones' letter to George Entwistle, dated September 7, 2001, the roof frame of the U.S. version of the Maranello is specially reinforced around the windshield to comply with FMVSS 216. Thus, although there is no difference between the U.S. and non-U.S. Maranello with respect to how the roof structure is affixed to the vehicle, the part itself differs.

HOW IT OF TOOMS IN HUIEN DIVOWED FULL

SUUUUUU 10 70001827# 1・87/と.

MAYER, BROWN & PLATT

Luke Loy November 14, 2001 Page 3

5. Identify differences in the rear frame assembly between the U.S. and non-U.S. version vehicle for both the 360 and the 550 vehicles.

Ferrari SpA has today informed us that, contrary to our statements in our letter to Mr. George Entwistle, dated September 7, 2001, the openings for the mounting of components on the rear frames of the U.S. and non-U.S. versions of the 360s and 550s are identical. However, as also noted in that letter, the U.S. versions of the 360s and 550s are fitted with a child seat tether anchorage. The non-U.S and non-Canadian versions of the 360s and 550s do not have such an anchorage affixed to their rear frames. Moreover, for compliance with U.S. regulations, the U.S. versions of the 360s have additional equipment and components (for the fuel evaporative system, the secondary air injection system, and the fuel recirculation system) mounted on the rear frame assembly. Compliance testing under FMVSS Nos. 208 and 301, and other relevant safety standards, for the 360s and 550s has been conducted with rear frames that have these additional components and equipment, and it is not possible to conclude with assurance that the non-U.S. 360s and 550s that lack them would perform like the U.S. versions in crash tests and other tests.

In light of this information, we assume that we need not provide exploded view drawings of the rear frames of the U.S. and non-U.S. versions of the 360s and 550s.

* * *

Because the information in this letter and the attachments hereto is publicly available, FNA will not be filing a request for confidential treatment with the Office of Chief Counsel, and, accordingly, will not object if the letter and attachments are placed in the public docket in their entirety.

We hope that this information is responsive to your request and will assist the agency in making its determination with respect to the petitions at issue in these dockets. If you need further information or have any further questions, please don't hesitate to contact Mr. Wertheim by fax ((202) 541-0038), phone ((201) 816-2713) or e-mail (dwertheim@ferrariusa.com).

Sincerely

Adam C. Sloane

cc: David Wertheim


Atts.

ATTACHMENT 1

550 Мата	mello - 125 - Alr	-bag	
1	165024	1	DRIVER SIDE AIR-BAG -Not for USA,CDN, AUS and J-
			-Not as spare part now- -Replaced by 661205,
1	661205	i	DRIVER SIDE AIR-BAG
		ě	-Not for USA,CDN, AUS and J- DRIVER SIDE AIR-BAG
1	174131	1	-Valid for USA, CDN, AUS and J-
			-Not as spare part now-
	004000	1	-Replaced by 661206 DRIVER SIDE AIR-BAG
1	661206.,	,	-Valid for USA,CDN, AUS and J-
2	127494	2	WASHER
3	14499324	2	WASHER
4	64882800	2	SCREW
5	647671	1	PASSENGER SIDE AIR-BAG -Not for USA, CDN, GB, AUS and J-
5	654047	1	PASSENGER SIDE AIR-BAG
_	050004		-Valid for USA, CON and J- PASSENGER SIDE AIR-BAG
5	652 081	1	-Valid for G8-
5	654048	1	PASSENGER SIDE AIR-BAG
			-Valid for AUS-
6	65174600	1	R.H. BRACKET
7	65174800	1	L.H. BRACKET
6	62940900	6. 4	SCREW NUT
9 10	1403961 4 1 64645	1	AIR-BAG CONTROL UNIT
10	104040	•	-Not for USA and CON-
10	174153	f	AIR-BAG CONTROL UNIT
	407404	•	-Valid for USA and CDN-
11	127494	2 2	WASHER SCREW
12 (3	64882800 160855	i	GROUND CABLE
14	16466 5	i	CABLES FOR AIR-BAG CONNECTION
, -	10-1000	•	-Not for GD-
14	(713 8 7	•	CABLES FOR AIR-BAG CONNECTION
15	163826	1	-Valid for GD- PASSENGER SIDE AIR-BAG
. 0	100000	•	RESISTOR
16	65321700	2	BRACKET
17	64892800	4	SCREW
18	10615474	4	WASHER
19	12640624	4	WASHER
20	6514 2000	1	AIRBAGICHILDREN SEAT INCOMPATIBILITY PLATE
21	12858090	ſ	AIR-BAG MAINTENANCE
			AUTO-ADHESIVE PLATE
			-Not for USA, AUS and CDN- -Veild till car Ass. Nr. 31238-
21	65910700	1	AIR-BAG MAINTENANCE
	00014700	,	AUTO-ADHESIVE PLATE
			-Not for USA, AUS and CDN-
			-Velld from car Ass. Nr. 31237-
21	64499400	1	AIR-BAG MAINTENANCE
			AUTO-ADHESIVE PLATE -Valid for USA and AUS-
21	64541700	1	AIR-BAG MAINTENANCE
	OHOH ITWO	1	AUTO-ADHESIVE PLATE
			-Valid for CDN-
22	65424000	1	AIR-BAG PRESENCE PLATE
77	64764500	2	-Valid for USA and AUS- AIR-BAG USE AUTO-ADHESIVE
23	0420U		PLATE
			_

-Not far USA, AUS and CUN-	AIR-BAG PRESENCE PLATE Valid for USA and AUS.	AIR-BAG PRESENCE PLATE	AIR-BAG USING AUTO-ADHESIVE PLATE	.valid for USA and AUS- AIR-BAG USING AUTO-ADMESIVE PLATE	Valid for CDN-
	-	-	-	-	
	65423700	64541600	65423800	64541500	
	23	ន	*	54	

See "INNER TRIMS CAR CODES" table for codes of parts covered in teather or maguatia.




44400000000 IO 700010444

550 Mera	nello - 124 - Instrument	s panel	
1	6475 83	1	COVERED DASHBOARD WITH INSTRUMENTS -Not for GD-
-	651 13B	1	COVERED DASHBOARD WITH INSTRUMENTS
•	CARCCE	•	-Valid for GD- L.H. LATERAL COVER
2	647665		R.H. LATERAL COVER
3	647668	1	PLATE
	64712800	4	SCREW
4	15914877	9 4	
5	14188181		RETAINER
8	63204200	1	R.H. PLATE L.H. PLATE
7	63 204 300 64707400	1	AIR DUCTING
,	04707400	,	-Not for GD-
	65024100	1	AIR DUCTING
-	03024100	•	-Valid for GD-
8	63202100	1	LOWER ENCLOSURE
9	64706200	1	L.H. AIR DUCTING
3	44100200	•	-Not for GD-
_	65212200	1	LH. AIR DUCTING
	00212200	•	-Valid for GD-
10	64706300	1	R.H. AIR DUCTING
10	04100000	•	-Not for GD-
_	65212100	1	R.H. AIR OUCTING
-	03212100	•	-Valid for GD-
11	6475B200	1	L.H. SLEEVE
1.	04120200	'	-Nat for GD-
	65217300	1	L.H. SLEEVE
•	USELISM	ı	-Valid for GD-
	64758100	1	R.H. SLEEVE
-	041.20100	•	-Not for GD-
_	65216600	•	R H. SLEEVE
		•	-Valid for GD-
12	13000890	2	SCREW COLLAR
13	64719500	ī	AIR DUCT CONNECTION
14	64701500	1	DASHBOARD R.H. LATERAL
• •	• • • • • • • • • • • • • • • • • • • •	•	FIXING BRACKET
	64701700	1	DASHBOARD L.H. LATERAL
	• • •	•	FIXING BRACKET
15	64720000	1	BRACKET
	• • • • • • • • • • • • • • • • • • • •	•	-Not for GD-
-	65049700	1	BRACKET
	***************************************	•	-Valid for GD-
16	64703200	1	R.H. BRACKET
			-Not for GD-
	65024700	(R.H. BRACKET
			-Valld for GD-
17	647591_	1	L.H. LOWER COVER
			-Not for GD-
	650250	1	R.H. LOWER COVER
		•	-Valld for GO-
18	64568000	1	L.H. SIDE BRACKET
			-Not for GD-
_	65049400	1	R.H. SIDE BRACKET
	-		-Valid for GD-
19	645882	1	GLOVE BOX SHUTTER
			-Not for GD-
	650498	1	GLOVE BOX SHUTTER
			-Valid for GD-
20	64653900	1	TIE ROO
			-Not for GD-
	65166800	t	TIE ROD
			-Valid for GD-

21	63768800	•	GLOVE BOX LOCK
	64926500	ì	PUSH BUTTON
22		i	FORK
23	63769000	1	PLATE
24	63768900		
25	64653700	ſ	DOOR FRAME
			-Not for GD-
	65024900	1	DOOR FRAME
			-Valid for GD-
26	64767600	- 1	DASHBOARO DRAWER
20	04707000	•	-Not for GD-
	aE102000	1	DASHBOARD DRAWER
•	65 103900		
		_	-Valid for GD-
27	64653200	1	BOX HINGE
			-Nat for GD-
	65026800	•	BOX HINGE
	00020000	·	-Valid for GD-
26	63765700	1	LEVER
		•	DOOR SPRING
29	63876700	!	
30	64580800	1	BRACKET
			-Not for GD-
-	65024600	1	BRACKET
			-Valid for GD-
31	647596		COVERED DASH BOARD
J,	Q-41 Q0 D	•	-Not for GD-
			-Not as spare part now-
			-Replaced by 647595
-	647 59 5	ŧ	COVERED DASH BOARD
			-Not for GD-
-	651043	1	COVERED DASH BOARD
			-Valid for GD-
32	5218630 0	2	GASKET
33	173939	ī	MICRO-SWITCH
34	139517	i	ROOF LIGHT
-			
35	65258900	1	STRIKER
36	61524300	2	NUT
37	61524200	4	WASHER
38	652 12000	3	SCREW
39	63352600	5	AIR OPENING
40	65361300	2	PIN
41	64587400	1	UNION FROM EVAPORATOR UNIT
41	04387400	1	
			TO AIR OPENING
			-Not for GD-
•	65024300	1	UNION FROM EVAPORATOR UNIT
			TO AIR OPENING
			-Valid for GD-
42	171800	1	INTERMEDIATE BRACKET
42	17 1000	,	-Valid for GD-
43	168961	1	OBDII CONNECTOR FIXING BRACKET
			-Valid for USA and CDN-
44	15688170	2	SCREW
			-Valid for USA and CDN-
45	14202580	2	BLOCK
45	14505000	•	-Valid for USA and CDN-
40	40510004		
40	10519224	2	WASHER
			-Valid for USA and CDN-
47	113647	2	NUT
			-Valid for USA and CDN-
48	12637824	2	WASHER
	VB 1	-	-Valid for USA and CON-
49	63765300	1	STRIKER FIXING PLATE
		3	
50	65879900	3	PIN

See "INNER TRIMS CAR CODES" table for codes of parts odvered in leather or maquatie.




ATTACHMENT 2

360 Moden	a - 11 - FUEL TANKS /	NO UNION	
1	175418	1	L.H. FUEL TANK
	404270	1	-Not as spare part replaced by 181270- L.H. FUEL TANK
1	181270	'	-Replaces 17541B-
1	179524	1	-Notion USA MY 2000 and CDN MY 2000- L.H. FUEL TANK
1	1/9024	•	-Valid for USA MY 2000 and CON MY 2000-
2	175419	1	R.H. FUEL TANK -Not for USA, CDN and AUS-
			-Not as spare part replaced by 181326-
2	161328	1	R.H. FUEL TANK -Not for USA, CDN and AUS-
			-Replaces 175419-
2	181338	1	R.H. FUEL TANK -Valid for USA, CDN and AUS-
3	177638	•	UNION
			-Valid for catalyzed cars- -Not for USA, CDN and AUS-
3	180059	,	UNION
			-Valid for not catalyzed cars-
3	185264	1	-Not for USA, CDN and AUS- UNION
			-Valid for USA, CDN and AUS-
4 5	64666900 12601274	3 3	SCREW WASHER
0	177572	1	COMPLETE PLUG
€	180118	1	-Not as spare part replaced by 180118- COMPLETE PLUG
		·	-Replaces 177572-
7 8	172899 177640	1	GASKET UNION-TANK CONNECTING
•	177040	•	PIPE
0	178665	1	-Not for USA, CDN and AUS- UNION-TANK CONNECTING
U	176065	'	PIPE
9	141033	2	-Valid for USA, CON and AUS- GASKET
•	111055		-Not for USA, CDN and AUS-
10	165398	2	SCREW COLLAR -Nol for USA, CDN and AUS-
10	180957	7	SCREW COLLAR
11	174101		-Valid for USA, CDN and AUS- VENT PIPE FROM TANK TO
11	174101	•	UNION
12	142105	2	Not for USA, CDN and AUS- GASKET
12	142100		-Not for USA, CDN and AUS-
13	164015	2	SCREW COLLAR
14	180364	1	-Not for USA, CON and AUS L.H. VALVE WITH PIPE
			-Not for USA MY 2000 and CDN MY 2000-
14	180608	1	L.H. VALVE WITH PIPE -Valid for USA MY 2000 and CDN MY 2000-
15	169938	2	GASKET
18	180382	1	R.H. VALVE WITH PIPE Not for USA MY 2000 and CDN MY 2000-
16	160608	1	R.H. VALVE WITH PIPE
	470544		-Valid for USA MY 2000 and CON MY 2000-
17	179511	1	DISAREATOR -Not for USA MY 2000 and CDN MY 2000-
17	182964	•	DISAREATOR
18	10902411	2	-Valid for USA MY 2000 and CON MY 2000- SCREW
19	127494	2	WASHER
20 21	10523424 166602	2	WASHER SLEEVE
	12000300	4	SCREW COLLAR


í
'n
,,

23	178347	1	TANKS CONNECTION PIPE
			Not as spare part replaced by 181695.
23	181695	1	TANKS CONNECTION PIPE
			-Replaces 178347-
24	123622	1	GASKET
25	148045	1	THREADED PLUG
26	177437	6	RUBBER THICKNESS
27	114277	2	RUBBER HOSE
28	168220	4	SCREW COLLAR
29	180067	1	WATER EXHAUST TUBE
30	64872000	1	SLEEVE
31	65064500	1	GASKET
32	104919	+	RING NUT
33	177553	1	CLAMP
34	179137	•	FUEL PRESSURE SENSOR
			-Valid for USA, CDN and AUS-
35	115140	1	RUBBER HOSE
			-Valid for USA, CON and AUS-
36	10977714	1	SCREW
			-Valid for USA, CON and AUS-
37	12601174	1	WASHER
			-Valid for USA, CDN and AUS-
38	12637824	1	WASHER
			-Valid for USA, CDN and AUS-



550 Maranello - 12 - Fuel tank - Not for USA M.Y. 99, USA M.Y. 2000, CDN M.Y. 99 and CDN M.Y. 2000-165129 FUEL TANK COMPLETE FUEL LEVEL 2 168738 INDICATOR CONTROL 3 154802 GASKET RING NUT 121435 5 172953 FILLER -Valid III Ass, Nr. 24856--Not for not catalyzed cars-171278 FILLER -Valid from Ass. N° 24857--Not for not catalyzed cars-173482 FILLER -Valid for not catalyzed cars-6 174095 GASKET SCREW 62926700 3 8 12501274 3 WASHER RUBBER PROTECTION 62943200 9 10 142790 PLUG -Valid till Ass. Nr. 24856--Not as spare part now-Replaced by 175708-175708 PLUG 171324 PLUG -Valid from Ass. Nr. 24857--Not as spare part now--Replaced by 180321-PLUG 180321 11 142792 GASKET -Valid IIII Ass. Nr. 24655--Not as spare part now--Replaced by 175709-GASKET 175709 GASKET 170822 -Valid from Ass. Nr. 24857--Not as spare part now--With complete plug 160321-FILLER-TANK CONNECTING 167131 12 PIPE SCREW COLLAR 13 170127 VENT PIPE FROM TANK TO 14 165132 FILLER 15 164015 SCREW COLLAR PIPE FROM FILLER TO VALVE 16 170156 17 13431570 SCREW COLLAR 169840 2-WAY VALVE 18 RUBBER PIPE 19 170546 20 13431870 SCREW COLLAR MOINU YAWE 170615 21 FUEL TANK FASTENER 22 172340 23 103447 PIN 24 10796440 SPLIT PIN THREADED TIE ROD 25 127529 26 10796440 SPLIT PIN 27 104030 NUT 62766300 CLIP 28 SCREW 29 10902224 WASHER 127494 30 10519424 WASHER 31 2 32 169683 DISAREATOR -Valid Iill car Ass. Nr. 30266--Not for USA M.Y. 99 and CDN M.Y. 99-178850 DISAREATOR -Valid from car Ass, Nr. 30267--Valid for USA M.Y. 99 and CON M.Y. 89-33 13434670 2 SCREW COLLAR 65083800 UNDER TANK SHIELD 34 10007474 SCREW

36	12643724	4	WASHER
		7	NUT WITH CAGE
37	60659100	4	
38	64783600	1	RUBBER PLUG
39	65084500	2	AIR DELIVERY TUBE TO TANK
40	12173190	4	SCREW COLLAR
41	148D45	ı	THREADED PLUG
42	123622	1	O.R. GASKET
43	65197700	1	EXHAUST PLASTIC HOSE
44	157411	1	RUBBER THICKNESS
45	167025	3	RUBBER THICKNESS
46	161032	1	EXHAUST PLASTIC HOSE
47	13423671	1	ELASTIC COLLAR
48	161490	2	SCREW COLLAR
49	169937	1	PIPE WITH VALVE
50	169839	2	VALVE
51	116762	2	RUBBER HOSE
52	13434670	Ž	SCREW COLLAR
53	169938	ā	GASKET
54	179851	1	RUBBER HOSE



550 Ma	ranello - 13 - Fuel tar	nk -Va 5 d for US	SA M.Y. 99, USA M.Y. 2000, CDN M.Y. 99 and CDN M.Y. 2000-
1	179176	1	FUEL TANK -Vaiot for USA M.Y. 99 and CDN M.Y. 99-
	404000	f	FUEL TANK
t	181926	ī	-Valid for USA N.Y. 2000 and CDN M.Y. 2000-
			-Not as spare part now-
			-Replaced by 186103-
1	186103	1	FUEL TANK
'	140 100	•	-Valid for USA M.Y. 2000 and CON M.Y. 2000-
2	168238	1	COMPLETE FUEL LEVEL
-	,		INDICATOR CONTROL
3	154802	•	GASKET
4	121435	1	RING NUT
5	171278	1	FILLER
			-Valid for USA M.V. 99 and CDN M.Y. 99-
5	181932	1	FILLER
			-Valid for USA M.Y. 2000 and CDN M.Y. 2003-
6	1740/35	1	GASKET
7	62926700	3	SCREW
8	12601274	3	WASHER
9	174093	1	FLANGE
10	180321	1	PLUG
11	180119	ŧ	GASKET
12	167131	1	FILLER-TANK CONNECTING
			PIPE
			-Valid for USA M.Y. 99 and CON M.Y. 99-
12	181977	1	FILLER-TANK CONNECTING
			PIPE
		_	-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
13	170127	2	SCREW COLLAR
14	165132	. 1	VENT PIPE FROM TANK TO
			FILLER
		_	-Valid for USA M.Y. 99 and CDN M.Y. 99-
14	182265	1	VENT PIPE FROM VAPOR SEPARATOR
			TO FILLER Valid for USA M.Y. 2000 and CON M.Y. 2000-
	44.4045	•	
15	164015	2	SCREW COLLAR -Vafid for USA M.Y. 99 and CDN M.Y. 99-
4.5	43412070	(COLLAR FOR SLEEVE
15	13432070	•	-Valid for USA M.Y. 2000 and CON M.Y. 2000-
16	125769	1	TEMPERATURE SENSOR
17	179321	ì	GASKET
18	179851	i	RUBBER HOSE
19	161490	i	SCREW COLLAR
20	179191	;	R.H. VALVE COMPLETED WITH
20	175137	•	PIPING
			-Valid for USA M.Y. 99 and CDN M.Y. 99-
20	181936	1	R.H. VALVE COMPLETED WITH
		•	PIPING
			-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
21	179191		L.H. VALVE COMPLETED WITH
• 1	11,5101	•	PIPING
			-Valid for USA M.Y. 99 and CDN M.Y. 99-
21	181935	1	L.H. VALVE COMPLETED WITH
• •	10 1303	•	PIPING
			-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
22	172340	2	FUEL TANK FASTENER
££	1125-10	•	-Valid for USA N.Y. 99 and CDN M.Y. 99-
22	161692	2	FUEL TANK FASTENER
	101044	•	-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
23	103447	2	PIN
24	10796440	4	SPLIT PIN
25	127529	2	THREADED TIE ROD
26	10795440	ž	SPLIT PIN
27	104030	2	NUT
28	62786300	ž	CLIP
29	10902224	2	SCREW
		-	-Valid for USA M.Y. 99 and CDN M.Y. 89-

29	10902124	2	SCREW
			-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
30	127494	2	Washer
			-Valid for USA M.Y. 99 and CDN M.Y. 99-
30	12639724	2	WASHER
			-Valid for USA M.Y. 2000 and CON M.Y. 2000-
31	10519424	2	WASHER
-		_	-Valid for USA MLY, 99 and CDN M.Y. 99-
31	127494	2	WASHER
		_	-Valid for USA M.Y. 2000 and CON M.Y. 2000-
32	178866	1	DISAREATOR
	***************************************		-Valid for USA M.V. 99 and CDN M.Y. 99-
32	181931	1	DISAREATOR
-	101401		-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
33	169937	•	VALVE COMPLETED WITH
33	100537	•	PIPING
			-Velid for USA M.Y. 99 and CDN M.Y. 99-
33	180469	1	VALVE COMPLETED WITH
.3.3	IBUAGS	•	PIPING
			Valid for USA M.Y. 2000 and CON M.Y. 2000-
34	65083800	1	UNDER TANK SHIELD
35	10902424	4	SCREW
36	12643724	- 7	WASHER
37	60659100	4	NUT WITH CAGE
38	64783600	ī	RUBBER PLUG
39	65084500	ż	AIR DELIVERY TUBE TO TANK
40	13000790	4	SCREW COLLAR
41	148045	1	THREADED PLUG
42	123822	i	O.R. GASKET
43	169938	à	GASKET
44	62943200	ĭ	RUBBER PROTECTION
45	14622387	ì	PLUG
40	14084307	Į.	-Va5d for USA M.Y. 2000 and CDN M.Y. 2000-
46	156682	2	LOWER THICKNESS
47	171163	î	PROTECTION SHEATH
41	171103	•	-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
48	183850	i	BRACKET
70	100000	•	-Va5d for USA M.Y. 2000 and CDN M.Y. 2000-
49	167025	1	FRONT THICKNESS
50	183585	ż	REAR THICKNESS
JU	103000	-	-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
51	157411	2	REAR THICKNESS
31	101411	4	-Vand for USA MLY. 99 and CDN MLY. 89-
51	183387	2	REAR THICKNESS
Ji	103201	•	-Valid for USA M.Y. 2000 and CDN M.Y. 2000-
			- 4 Billy 401 GOTCHILT, \$000 BIRD GOTT M. 1. \$000

